

ROOF MANAGEMENT PROGRAM

FACILITY:		2012	2013	2014	2015	2016	2017	2018
BUILDING DESIGNATION								
SECTION A		\$75,000.00	\$500.00	\$500.00	\$500.00	\$500.00	\$500.00	\$500.00
SECTION A2		\$35,000.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00	\$200.00
SECTION B		\$500.00	\$500.00	\$60,000.00	\$500.00	\$500.00	\$500.00	\$500.00
SECTION C		\$3,500.00	\$90,000.00	\$700.00	\$700.00	\$700.00	\$700.00	\$700.00
SECTION D		\$15,000.00	\$700.00	\$88,000.00	\$700.00	\$700.00	\$700.00	\$700.00
SECTION E		\$4,000.00	\$180,000.00	\$500.00	\$500.00	\$500.00	\$500.00	\$500.00
SECTION F		\$2,800.00	\$500.00	\$500.00	\$85,000.00	\$500.00	\$500.00	\$500.00
SECTION G		\$1,500.00	\$500.00	\$30,000.00	\$800.00	\$800.00	\$800.00	\$800.00
SECTION H		\$2,400.00	\$500.00	\$500.00	\$500.00	\$85,000.00	\$500.00	\$500.00
SECTION I		\$1,500.00	\$200.00	\$200.00	\$50,000.00	\$200.00	\$200.00	\$200.00
SECTION J		\$1,800.00	\$500.00	\$85,000.00	\$500.00	\$500.00	\$500.00	\$500.00
TOTALS:		\$143,000.00	\$274,600.00	\$266,100.00	\$139,900.00	\$90,100.00	\$5,600.00	\$5,600.00
ROOF CODE:			ROOF RESTORATION (COATING, SURFACING, ETC.)					
			REPAIRS TO CORRECT CURRENT DEFICIENCIES					
			GENERAL PREVENTATIVE MAINTENANCE PROGRAM					
NOTE:		ROOFING MEMBRANE WILL NEED TO BE TESTED TO ENSURE ADQUATE TENSILE STRENGTH EXISTS						
NOTE:		MOISTURE ANALYSIS MUST BE CONDUCTED TO VERIFY NO WET INSULATION IS PRESENT						